

RG58 and RG59/62 Coax Connector Kits



Everything you need to install RG58 connectors on your cable.

the crimping die.

3. Hold the handles closed to

4. Close the handles to crimp.

5. Open the tool handles and

6. Insert the crimped center

body with braid over

7. Slip the ferrule over the

8. Crimp the ferrule three

braid until the ferrule butts

against the connector body.

support sleeve.

times.

contact into the connector

remove the crimped contact.

grip the contact while

inserting the center

conductor.

works for your coax connections.

Key Features

Kit includes a crimp tool, and 20 each connectors, ferrules, and contacts.

Choose from RG58- or RG59/62-type coax connectors.

Lets you connect your coax cable to your coax devices.

Technically Speaking

The Coax Connector kits come complete with a manual crimp tool and 20 RG58 or RG59/RG62 BNC-type connectors, 20 ferrules, and 20 contacts. Choose one of these kits:

• RG58-Type (FTM700)

Assembling the connectors and attaching them to your cable is a simple. The plug connector consists of a plug body, a center contact, and a ferrule. Tubing is also provided with connectors that use air core dielectric cable. A typical assembly

procedure appears in Figure 2 Support sleeve of connector Ferrule





Braid support over connector support sleeve



Figure 2. Typical assembly procedure.

below.

A manual crimp tool (pictured in Figure 1 above) is used to crimp the contacts and ferrules included in your kit.

Follow these steps and your cables will be ready to connect to your coax equipment.

- 1. Slide the ferrule on the cable, then strip the cable to the dimensions shown in Figure 1 above. (The strip length is stamped on the tool.)
- 2. Open the tool handles and locate the center contact in

For these and other components...

Call our expert Technical Support Staff for all your cable and connector needs. They'll help you find the best equipment for your application.

Ordering Information

This information will help you place your order quickly.

PRODUCT NAME	ORDER CODE
Coax Connector Kits RG58-Type RG58 Cable (3m) NOTE: The kits include a crimp tool, 20 contacts, and 20 ferrules.	